

November 2011

ADL Firmware Version 3.04.2263

Key enhancements & fixes since the previous release (Version 3.02.2250)

- ID# 276, 720 Improved ACK/NAK support for Packet Switched protocol
- ID# 506 Support for addressing in the Transparent/EOT, Transparent/EOC and Packet Switched protocols
- ID# 608 Display duty cycle on the ADL Vantage and ADL Vantage Pro user interface (when TT450S is selected as protocol); display internal temperature on the ADL Vantage and ADL Vantage Pro user interface
- ID# 622 On the ADL Vantage/ADL Vantage Pro Device Status screen change “BW” to “Ch BW” to indicate the channel bandwidth of the programmed channel table
- ID# 698 Automatic Channel Selection feature for ADL Vantage (only). User can select any of the channels in the channel table or have the radio automatically select the channel with the strongest signal containing decipherable data
- ID# 736 Expanded repeater mode support among all protocols
- ID# 738 Serial buffer lockup fix for data rates faster than 1 Hz
- ID# 745,757 New antenna detection/VSWR measurement feature in ADL Vantage Pro. This feature is activated prior to first transmit. If VSWR>4:1, the ADL Vantage Pro will reduce its TX power to 2W and the user is notified to check the antenna. The user is also notified if no antenna is detected.
- ID# 758 FW files created to handle specific bootloader baud rates required by OEM products incorporating ADL radio modems
- ID# 761 Fixed defect in the Meaning of RX LED feature (switching between the two would cause the radio to get stuck on the “signal received” option
- ID# 768 To better support serviceability, ADL Vantage Pro does not go into power saving sleep mode when radio is in command mode
- ID# 777 Improved internal voltage sensor to prevent ADL Vantage Pro giving false low battery warnings and automatically shutting off
- ID# 778 Added new API command to get product serial number
- ID# 788 Update ADL Vantage/Vantage Pro User Guide

ID# 803 Fixed a defect that could cause RTCM 3.0 correction data packets to be rejected by the receiving radio. Note: this fix is in ADL firmware version 3.04.2280. If you use RTCM 3.0 corrections, you should upgrade to this version of firmware.

ADLCONF Software Version 3.04.2145

Key enhancements & fixes since the previous release (Version 3.02.2135)

- ID#692 Prevent the overwriting of radio S/Ns by the Restore Factory feature
- ID# 698 User can turn on the Auto Channel Selection feature in any ADL radio except the ADL Vantage Pro by choosing the "AUTOROVER" Mode on the Radio Link screen and then clicking "Program". After the radio finds the channel with the strongest signal and locks onto it, it will exit "AUTOROVER" mode and enter "MANUAL" mode.
- ID# 721 Reset TX power to Max TX Power when importing new .dat file
- ID# 753, 758 Revised the firmware upgrade function so that it can configure ADL radio modems embedded in products that are restricted to using specific baud rates
- ID# various Improvements in both functionality and display of the configuration files (*.txt) generated by the Print function
- ID# 773 Added new protocol: Stonex Type 1
- ID# 787 Update ADLCONF user guides (dealer and end user)